

Inspection Photos
Operator: Simcoe
Facility: 067-08812
Date: 9/20/2021



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of western fill slope. Revegetation is progressing with western wheatgrass, smooth brome, and crested wheatgrass. Erosion is occurring along the edges of the seeded area, at the toe of the slope.



Photo 3. Another view of erosion occurring along the edge of the western project area. Diverted stormwater flows are scouring soils and vegetation in the southwestern corner.



Photo 4. View of silt trap in the southwestern corner of the project area. This BMP is not adequate to contain diverted stormwater flows from the well pad, as evidenced by active down-slope erosion (Photo 3).



Photo 5. View of reference area comprised of sagebrush shrubland with snakeweed, James galleta, buckwheat, and penstemons in the understory.