

Inspection Photos
Operator: Simcoe
Facility: 067-06983
Date: 9/20/2021



Photo 1. View of project area from the southeastern corner facing center.



Photo 2. View of eastern project area from the southeastern corner facing northward. Dense kochia present needs management (ie: mowing) to encourage desirable vegetation. Revegetation is progressing with western wheatgrass, smooth brome, and crested wheatgrass.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of dense kochia growing on the well pad.



Photo 5. View of reference area (in background) comprised of irrigated grass field with western wheatgrass and mixed pasture grasses.