

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/29/2021

Submitted Date:

09/29/2021

Document Number:

695104872

FIELD INSPECTION FORMLoc ID 322219 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 74975

Name of Operator: SAN MARCO PETROLEUM INC

Address: 240 MILWAUKEE ST STE 200

City: DENVER State: CO Zip: 80206-

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Sheridan, John	303-905-5919	jsheridanvc@gmail.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209942	WELL	PR	03/01/2021	OW	043-06020	ADAMIC 1-20	PR

General Comment:

COMPLIANCE INSPECTOR PERFORMED A FOLLOW UP INSPECTION TO INSP. DOC #700300205. IT APPEARS THAT GAS LEAK AROUND WELLHEAD HAS BEEN ADDRESSED. SEE UPLOADED FLIR VIDEO. IT ALSO APPEARS THAT THE GAS VENTING FROM CRUDE OIL TANKS HAVE BEEN ADDRESSED. SEE UPLOADED FLIR VIDEO.

THE CORRECTIVE ACTION TO REMOVE THE TREE FROM INSIDE BURM HAS BEEN ADDRESSED. SEE UPLOADED INSP. PHOTOS.

THE CORRECTIVE ACTION FOR REPAIRING THE TANK BATTERY BURM HAS NOT BEEN ADDRESSED. SEE TANK SECTION.

THE BRADENHEAD ACCESS CORRECTIVE ACTION HAS NOT BEEN ADDRESSED. SEE EQUIPMENT INVENTORY SECTION.

THE CORRECTIVE ACTION FOR ROW APPEARS TO HAVE BEEN ADDRESSED.

NOTE: THE TWO CORRECTIVE ACTION GIVEN ON THIS DOCUMENT ARE ONGOING CA'S FROM PREVIOUS INSPECTION AND IMMEDIATE ACTION IS REQUIRED.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead

#

Comment:

PHOTO 5: CA for bradenhead access given in two previous FIR docs #695103790 & #700300205 and not performed.

Corrective Action:

Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).

Date:

Type: Pump Jack

1

Comment:

ELECTRIC DRIVEN PUMPJACK APPEARS TO BE OPERATING ON A TIMER

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

ELECTRIC SUPPLY LINE FOR PUMPJACK (POWER POLE, ELECTRIC METER AND BREAKER BOX).

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	OTHER	STEEL AST		38.378840,-105.128546
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity) 210 bbls

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	PHOTO 4: Berm beaten down on south end of battery affecting capacity. This is a corrective action on the previous inspection doc. #700300205 that has not been addressed. Corrective action time is immediate.			
Corrective Action:	Maintain berms per 603.o(3) to restore proper capacity and impermeability.			Date:

Inspected Facilities				
Facility ID: 209942	Type: WELL	API Number: 043-06020	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #700300205, THERE ARE CA'S THAT HAVE NOT BEEN ADDRESSED.	beardslt	09/29/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402828351	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5544812
695104873	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5544808
695104877	tank battery FLIR video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5544809
695104878	wellhead FLIR video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5544810