

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/30/2021

Submitted Date:

09/30/2021

Document Number:

699803671

FIELD INSPECTION FORMLoc ID 335098 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
13	WELL	PR	06/01/2006	GW	045-11667	PUCKETT PA 322-35	PR
264399	WELL	PR	01/19/2003	GW	045-08209	PUCKETT PA 22-35	PR
282142	WELL	PR	05/29/2006	GW	045-11687	PUCKETT PA 522-35	PR
282150	WELL	PR	05/01/2006	GW	045-11662	PUCKETT PA 422-35	PR

General Comment:**COGCC Inspection Report Summary**

On Thursday 9/30/21 at approximately 12:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC PUCKETT-66S95W /35SENW, Location #335098 in Garfield County Colorado.

While there, I observed normal production operations.

I contacted Mike Gardner of TEP and informed him of the 24 hour notice. He stated that the gauge hatch would be closed within the hour. During this inspection the following compliance issues were observed:

- 1) Horizontal separators includes glycol storage tank. Glycol storage tank is approximately 2'x3'x14' with an approximate capacity of 15 barrels. Glycol storage tank missing required information with a corrective action date of 12/30/21.
- 2) Gauge hatch open with a corrective action date of 10/1/21.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Horizontal separator includes glycol storage tank. Glycol storage tank is approximately 2'x3'x14' with an approximate capacity of 15 barrels. Glycol storage tank missing required information.		
Corrective Action:	All Tanks with a capacity of 10 Barrels or greater will be labeled with Name of operator, Operator's emergency contact telephone number, Tank capacity, Tank contents, and NFPA label or equivalent globally harmonized label.	Date:	12/30/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 2		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	200 BBLs	STEEL AST		39.482330,-107.969280	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
	Date:			

Venting:

Yes/No	YES		
Comment:	Gauge hatch open.		
Corrective Action:	Gauge hatches on atmospheric Tanks used for crude oil storage will be closed, latched, and sealed at all times.	Date:	10/01/2021

Flaring:

Type		
Comment:		
Corrective Action:		Date:



Inspected Facilities				
Facility ID:	13	Type:	WELL	API Number: 045-11667 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:
Facility ID:	264399	Type:	WELL	API Number: 045-08209 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:
Facility ID:	282142	Type:	WELL	API Number: 045-11687 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:
Facility ID:	282150	Type:	WELL	API Number: 045-11662 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Berms						
		Compaction				
Gravel						
Compaction						
		Sediment Traps				
Ditches						
		Berms				
		Ditches				
		Gravel				
Sediment Traps						

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Sign/Markers and venting for corrective actions.	depaoloc	09/30/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402829011	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5545406
699803672	Photos for Insp. #699803671	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5545401