

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/30/2021

Submitted Date:

10/01/2021

Document Number:

700703311

**FIELD INSPECTION FORM**

Loc ID 418623	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: PO BOX 370 City: PARACHUTE State: CO Zip: 81635				<b>Findings:</b> 20 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418619	WELL	PR	05/01/2012	GW	045-19780	Farris RWF 33-31	PR
418622	WELL	PR	03/01/2012	GW	045-19781	Farris RWF 444-31	PR
418624	WELL	PR	02/26/2012	GW	045-19782	Farris RWF 543-31	PR
418625	WELL	PR	03/31/2012	GW	045-19783	Farris RWF 34-31	PR
418626	WELL	PR	03/31/2012	GW	045-19784	Farris RWF 433-31	PR
418629	WELL	PR	03/31/2012	GW	045-19785	Farris RWF 333-31	PR
418630	WELL	PR	02/29/2012	GW	045-19786	Farris RWF 43-31	PR
418631	WELL	PR	03/31/2012	GW	045-19787	Farris RWF 44-31	PR
418633	WELL	PR	05/01/2012	GW	045-19788	Farris RWF 343-31	PR
418634	WELL	PR	02/29/2012	GW	045-19789	Farris RWF 533-31	PR
418637	WELL	PR	02/29/2012	GW	045-19790	Farris RWF 334-31	PR
418638	WELL	PR	03/01/2012	GW	045-19791	Farris RWF 344-31	PR
418639	WELL	PR	03/31/2012	GW	045-19792	Farris RWF 443-31	PR
418640	WELL	PR	03/01/2012	GW	045-19793	Farris RWF 434-31	PR

**General Comment:**

COGCC Inspection Report Summary

On Thursday 9/30/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RWF 34-31, at Location # 418623 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.

During this inspection the following compliance issues were observed:

1. Location shows signs of lack of stabilization/erosion behind separators
2. Missing bull plugs/caps on load out lines
3. Three quad unit horizontal separators includes 8 glycol storage tanks, approximately 174" x 33" x 42" = 25 BBLS each, storage vessels contain no labeling to specify capacity or chemical hazard information.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Three quad unit horizontal separators includes 8 glycol storage tanks, approximately 174" x 33" x 42" = 25 BBLS each, storage vessels contain no labeling to specify capacity or chemical hazard information.		
Corrective Action:	Install proper labeling		Date: 01/03/2022
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Missing bull plugs/caps on load out lines		
Corrective Action:	Comply with rule 603.i.		Date: 11/01/2021
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Bradenhead	# 14		corrective date
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks in plastic containments		
Corrective Action:		Date:	
Type: Plunger Lift	# 14		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate



Inspected Facilities									
Facility ID:	418619	Type:	WELL	API Number:	045-19780	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	418622	Type:	WELL	API Number:	045-19781	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	418624	Type:	WELL	API Number:	045-19782	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	418625	Type:	WELL	API Number:	045-19783	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	418626	Type:	WELL	API Number:	045-19784	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	418629	Type:	WELL	API Number:	045-19785	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	418630	Type:	WELL	API Number:	045-19786	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	418631	Type:	WELL	API Number:	045-19787	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	418633	Type:	WELL	API Number:	045-19788	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	418634	Type:	WELL	API Number:	045-19789	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	418637	Type:	WELL	API Number:	045-19790	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	418638	Type:	WELL	API Number:	045-19791	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	418639	Type:	WELL	API Number:	045-19792	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	418640	Type:	WELL	API Number:	045-19793	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [Lack of stabilization/erosion on cut slope behind separators](#)Corrective Action: [Install or repair required BMPs](#)

Date: 11/01/2021

**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402829219	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5545718">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5545718</a>
700703318	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5545711">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5545711</a>