

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2021

Submitted Date:

10/01/2021

Document Number:

700900758

**FIELD INSPECTION FORM**

Loc ID 320365 Inspector Name: Finkenbinder, Chane On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10711  
Name of Operator: PAINTED PEGASUS PETROLEUM LLC  
Address: 16820 BARKER SPRINGS RD #521  
City: HOUSTON State: TX Zip: 77084

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		khubbard@P3Petro.com	
		jmustacchia@p3petro.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203552	WELL	SI	12/01/2019	GW	001-09112	HELIX 1	SI

**General Comment:**

*(This area is currently blank for general comments.)*

**Location**

Overall Good:

Emergency Contact Number: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds throughout location.		
Corrective Action:	Location is within a designated setback, remove trash, debris and weeds per Rule 604.c. (2)P. Corrective Action Date 10/15/2021. See all attached photos 1 through 3.		Date: 10/15/2021

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:	Chain link		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Chain link		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	pipe		
Corrective Action:			Date:

**Equipment:**

Type	#		corrective date
Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	PLASTIC AST		,
Comment:	<input type="text"/>				

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares berm with crude				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.855276,-104.598530
Comment:					
Corrective Action:					
Date:					

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

**AirsID**

API Number	API Number	AirsID
001-09112		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			
Date:			

**Flaring:**

Type	
Comment:	
Corrective Action:	
Date:	

**Inspected Facilities**

Facility ID: 203552 Type: WELL API Number: 001-09112 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: Appears to be plumbed to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On Friday September 15, 2021. At approximately 10:45am. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Helix 1, Painted Pegasus Petroleum LLC, at API # 001-09112 in Adams County Colorado. While there, I observed a shut in well. During this inspection the following possible compliance issues were observed: Weeds throughout location. Location is within a designated setback, remove trash, debris and weeds per Rule 604.c.(2)P. Corrective Action Date 10/15/2021. See all attached photos 1 through 3. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p>	finkenbc	10/01/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402829335	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5545817">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5545817</a>
700900759	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5545814">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5545814</a>