

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/07/2021

Submitted Date:

10/07/2021

Document Number:

699503243

FIELD INSPECTION FORM

Loc ID 320084 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10711

Name of Operator: PAINTED PEGASUS PETROLEUM LLC

Address: 16820 BARKER SPRINGS RD #521

City: HOUSTON State: TX Zip: 77084

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		khubbard@p3petro.com	
		jh@p3petro.com	
		JM@p3petro.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202572	WELL	SI	11/01/2020	OW	001-07977	ELEANOR ARNOLD B 1	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds unmanaged on location, unused tubing next to wellhead see pics		
Corrective Action:	Comply with COGCC housekeeping rules	Date:	11/07/2021
Type	OTHER		
Comment:	Stained soil by wellhead, loadout lines on tank.		
Corrective Action:	Comply with COGCC housekeeping rules	Date:	07/27/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	6' Chainlink		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 1		corrective date
Comment:	automation		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Heated separator		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		

Comment:	Marked with metal fence post		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	Open Top		,	
Comment:	placards are facing, may need to be replaced soon.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with oil tank				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 202572 Type: WELL API Number: 001-07977 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/27/2020 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Annual bradenhead test is not current. Provide bradenhead monitoring data. Contact COGCC engineering. 10/17/2021

Corrective Action: Comply with COGCC annual bradenhead testing rules. Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 10/7/21 at approximately 1230I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Eleanor Arnold B 1</p> <p>Company Name- Painted Pegasus</p> <p>API- 05-001-07977</p> <p>In Adams County Colorado.</p> <p>While there, I observed</p> <p>This is a follow up inspection from document # 700900200 Corrective Actions are Delinquent</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil by wellhead, loadout lines on tank.</p> <p>Comply with COGCC housekeeping rules 7/27/20</p> <p>Weeds unmanaged on location, unused tubing on ground next to wellhead see pics</p> <p>Comply with COGCC housekeeping rules 11/7/21</p> <p>Annual bradenhead test is not current. Provide bradenhead monitoring data. Contact COGCC engineering.</p> <p>Comply with COGCC annual bradenhead testing rules. 10/17/21</p> <p>Tubing was removed from this well, and has one joint used to install wraparound wellhead.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p>	medinaj	10/07/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503244	Inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5550185