

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /30SESW

Location ID: 334060



Photo #5027 from entrance to location.



Photo #5028 from entrance to location.

Inspection Photos  
Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /30SESW  
Location ID: 334060



Photo #5029 No battery sign located at the tank battery.

Photo #5030 Glycol storage tank missing required information.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /30SESW

Location ID: 334060



**Photo #5031 Flowline heating insulation open ended and not capped.**