

Inspection Photos

API: 071-07604

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07604 | Date: 10/12/2021

Inspection Photos



Photo 1. Facing east toward the access road stream crossing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07604 | Date: 10/12/2021

Inspection Photos



Photo 2. Facing toward the disturbance area along the road side. All disturbed areas along the road side need to be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07604 | Date: 10/12/2021

Inspection Photos



Photo 3. There are multiple culverts installed and rock rip/rap was installed for bank stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07604 | Date: 10/12/2021

Inspection Photos



Photo 4. There is a black plastic pipe extending out of the ground on the east side of stream crossing. This needs to be removed or repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07604 | Date: 10/12/2021

Inspection Photos



Photo 5. Facing southeast along the access road. The culverts along the access road are filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07604 | Date: 10/12/2021

Inspection Photos



Photo 6. The culverts along the access road are filled in with sediment causing stormwater erosion down the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07604 | Date: 10/12/2021

Inspection Photos



Photo 7. Facing back down the road. There is erosion along the road side and stormwater is bypassing culverts which will cause further erosion. BMP's need to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07604 | Date: 10/12/2021

Inspection Photos



Photo 8. Another culvert further along the road is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07604 | Date: 10/12/2021

Inspection Photos



Photo 9. Erosion along the roadside has exposed a pipeline. Arrow points to 4.5 ft. shovel.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07604 | Date: 10/12/2021

Inspection Photos



Photo 10. Facing southeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07604 | Date: 10/12/2021