

Inspection Photos

API: 071-08082

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08082 | Date: 10/12/2021

Inspection Photos



Photo 1. Facing east toward the access road stream crossing. The road side area was repaired and rock check dams were installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 10/12/2021

Inspection Photos



Photo 2. Facing back southwest. There is a pile of cement debris that needs to be removed. This area of disturbance needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 10/12/2021

Inspection Photos



Photo 3. Facing southwest toward the access road. This area of erosion has not been repaired and stabilized. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 10/12/2021

Inspection Photos



Photo 4. Facing back down the road. The erosion along the road side has not been repaired and stabilized. Arrow points to 4.5 ft. shovel.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 10/12/2021

Inspection Photos



Photo 5. Further up the access road. There is stormwater erosion across the road. This area may need a culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 10/12/2021

Inspection Photos



Photo 6. Facing toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 10/12/2021