

Inspection Photos

API: 071-07085

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07085 | Date: 10/12/2021

Inspection Photos



Photo 1. Facing south toward the access road stream crossing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 10/12/2021

Inspection Photos



Photo 2. There are two culverts installed at the stream crossing. This appears to be inadequate as the prior cement culvert shown in the photo on the right had 3 large culverts.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 10/12/2021

Inspection Photos



Photo 3. Facing northwest at the stream crossing. There is no bank stabilization at the outlet side.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 10/12/2021

Inspection Photos



Photo 4. Facing south along the access road. All disturbed areas along the road side need to be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 10/12/2021

Inspection Photos



Photo 5. Facing southeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 10/12/2021