

Inspection Photos

Operator: Kinder Morgan
API: 033-06133
Date: 10/11/2021



Photo 1. View of project area from the well pad entrance facing center. Well pad is not reclaimed.



Photo 2. View of the western project area from the southwestern corner facing northward. Per communication with operator, frac tank placed on vegetation area to provide water to livestock by leasee. Frac tank is choking vegetation in the interim reclamation area.



Photo 3. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with blue grama, western wheatgrass, and squirreltail.



Photo 4. View of reference area comprised of Ponderosa pine woodland with serviceberry and gambel oak shrubland, and an understory of black sage, western wheatgrass, and James galleta.