

## Inspection Photos

Location Name: UPRR 60 PAN AM D 4

Location ID: 320069

Oct 11, 2021 at 2:41:14 PM  
39.975701,-104.473112  
3450 E 160th Ave  
Greeensburg CO 80643  
United States  
COGCC



**Pic 1 tank, weeds unmanaged, sign needs to be fixed.**

Oct 11, 2021 at 2:41:32 PM  
39.975681,-104.473378  
3450 E 160th Ave  
Greeensburg CO 80643  
United States  
COGCC



**Pic 2 wellhead, sign needs to be re-attached to wellhead**



## Inspection Photos

Location Name: UPRR 60 PAN AM D 4

Location ID: 320069

Oct 11, 2021 at 2:42:46 PM  
39.975623,-104.473485  
3450 E 160th Ave  
Greeensburg CO 80643  
United States  
COGCC



**Pic 3 wellhead, bradenhead is not plumbed to surface**

Oct 11, 2021 at 2:42:52 PM  
39.975623,-104.473485  
3450 E 160th Ave  
Greeensburg CO 80643  
United States  
COGCC



**Pic 4 wellhead only has 4 bolts securing flange from wellhead to Christmas tree. Mechanical issue.**



## Inspection Photos

Location Name: UPRR 60 PAN AM D 4

Location ID: 320069

Oct 11, 2021 at 2:44:39 PM  
39.975844,-104.473224  
3450 E 160th Ave  
Greeensburg CO 80643  
United States  
COGCC



**Pic 5 Separator,**

Oct 11, 2021 at 2:44:53 PM  
39.975872,-104.473078  
3450 E 160th Ave  
Greeensburg CO 80643  
United States  
COGCC



**Pic 6 Open top tank, unable to visually inspect netting due to weed growth**