

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/11/2021

Submitted Date:

10/11/2021

Document Number:

699503253

FIELD INSPECTION FORM
 Loc ID 320069 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10711

Name of Operator: PAINTED PEGASUS PETROLEUM LLC

Address: 16820 BARKER SPRINGS RD #521

City: HOUSTON State: TX Zip: 77084

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
		khubbard@p3petro.com	
		JH@p3petro.com	
		jm@p3petro.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202488	WELL	SI	09/01/2020	GW	001-07893	UPRR 60 PAN AM D 4	SI

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	Wellhead flange only has 4 bolts installed. All bolts need to be installed on flanged connections.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 10/26/2021
Type	OTHER		
Comment:	Weeds unmanaged on location, Unable to visually inspect equipment due to weed growth.		
Corrective Action:	Comply with COGCC housekeeping rules		Date: 07/27/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	4' barb wire around tanks and separator		
Corrective Action:			Date:

Equipment:

			corrective date
Type: Ancillary equipment	# 1		
Comment:	Plunger automation		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 1		
Comment:	Marked with production tubing pipe.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	#		
Comment:	not plumbed to surface		
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 1	
Comment:	unable to visually inspect due to weed growth	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			Open Top		,
Comment:	Unable to visually inspect due to weed growth				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Unable to inspect due to weed growth			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	unable to properly inspect due to weed growth			
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 202488 Type: WELL API Number: 001-07893 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 06/25/2020

Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Annual Bradenhead test is not current. Contact COGCC engineering. Provide monthly monitoring data.

10/21/2021

Corrective Action: Comply with COGCC annual bradenhead testing rules. 10/21/21

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 10/11/21 at approximately 1330 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- ANN 34-12</p> <p>Company Name- Painted Pegasus</p> <p>API- 05-001-07748</p> <p>In Adams County Colorado.</p> <p>While there, I observed PR well</p> <p>This is a follow up inspection from document #700900230 Corrective Actions are Delinquent</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds are unmanaged on location. Unable to visually inspect berms, and netting on open top tank due to weed growth.</p> <p>Comply with COGCC housekeeping rules 7/27/20</p> <p>Wellhead flange only has 4 bolts installed. All bolts need to be installed on flanged connections.</p> <p>Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.10/26/21</p> <p>Annual Bradenhead test is not current. Contact COGCC engineering</p> <p>Comply with COGCC annual bradenhead testing rules. 10/21/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p>	medinaj	10/11/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503254	Inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5556534