



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Weeds unmanaged on location, stained soil near load out line, and separator, mechanical issue with load out line valve, and separator.		
Corrective Action:	Comply with COGCC housekeeping rules.	Date:	04/24/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Red agricultural fencing		
Corrective Action:		Date:	

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Vertical Heated Separator	# 1				
Horizontal Heated Separator	# 2				
Ancillary equipment	# 1	Plunger lift automation			
Bird Protectors	# 3				
Plunger Lift	# 1				

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		,
Comment: Unable to inspect netting due to water					

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment: Unable to inspect due to weed growth on location				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment: unable to inspect due to weed growth on location				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 202703 Type: WELL API Number: 001-08108 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well has been shut in since 7/1/2017. Well is in need of MIT. Contact COGCC engineering.

Corrective Action: Well must be either:  
1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each shut-in well within two (2) years of the initial shut-in date or  
2) Be properly plugged and abandoned . Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report.

Date: 10/15/2021

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: According to COGCC data no bradenhead test is on file for this well. Annual bradenhead test is not current. Contact COGCC engineering, provide monthly monitoring data.

10/25/2021

Corrective Action: Comply with COGCC annual bradenhead testing rules.

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On 10/14/21 at approximately 1500 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Handke 1 Company Name- Overland Resources API- 05-001-08108 In Adams County Colorado. While there, I observed shut in well. This is a follow up inspection from document # 699501151, 700900171 Corrective Actions are Delinquent During this inspection the following possible compliance issues were observed: According to COGCC data no bradenhead test is on file for this well. Annual bradenhead test is not current. Contact COGCC engineering, provide monthly monitoring data. Comply with COGCC annual bradenhead testing rules. 10/25/21 Well has been shut in since 7/1/2017. Well is in need of MIT. Contact COGCC engineering. Well must be either: 1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each shut-in well within two (2) years of the initial shut-in date or 2) Be properly plugged and abandoned . Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report. 10/15/21 Weeds unmanaged on location, stained soil near load out line, and separator, mechanical issue with load out line valve, and separator. Comply with COGCC housekeeping rules. 4/24/20 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	10/15/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503266	Inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5556540">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5556540</a>