

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402842972

Date Received:
10/15/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10409
Name of Operator: PEAKVIEW OPERATING COMPANY LLC
Address: 1001 17TH ST SUITE 1050
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>
<u>Wise, Wayne</u>		<u>wwise@peakviewenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 694500367
Inspection Date: 08/26/2021 FIR Submit Date: 08/27/2021 FIR Status: _____

Inspected Operator Information:

Company Name: PEAKVIEW OPERATING COMPANY LLC Company Number: 10409
Address: 1001 17TH ST SUITE 1050
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 312916

Location Name: VOLOSHIN-MORTON-66N90W Number: 8NESE County: MOFFAT
Qtrqr: NESE Sec: 8 Twp: 6N Range: 90W Meridian: 6
Latitude: 40.491554 Longitude: -107.509189

FACILITY - API Number: 05-081-00 Facility ID: 222829

Facility Name: VOLOSHIN-MORTON Number: 1 (-8)
Qtrqr: NESE Sec: 8 Twp: 6N Range: 90W Meridian: 6
Latitude: 40.491554 Longitude: -107.509189

CORRECTIVE ACTIONS:

1 CA# 155258

Corrective Action: Assure that tank secondary containment is adequate per 603.o. evaluate capacity and permeability of secondary containment. Date: 11/03/2021

Response: CA COMPLETED Date of Completion: 09/09/2021

Operator Comment: The west wall of the containment berm was extended aproximately 10' to the west. The inside of the berm was cleaned out and the excavated material used to build up the eroded walls. Clean "road base" material was brought in and used to increase the wall height of the entire berm.

COGCC Decision: _____

COGCC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment: The bent horizontal 2" flowline noted in Photo 14 was cut and capped Sept 7 2021. During initial excavation activity in August, the same 2" line was cut and capped.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Wayne Wise

Signed: _____

Title: Operations Engineer

Date: 10/15/2021 3:36:12 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files