

Inspection Photos
Location Name: Jacobucci #4
Location ID: 318728



Photo 1 loc pic



Photo 2 loc pic

Inspection Photos
Location Name: Jacobucci #4
Location ID: 318728



Photo 3 Mechanical issue electric panel sinking and wires showing



Photo 4 Mechanical issue well head leaking.