

Inspection Photos
Location Name: UPRR 43 pan AM I#25
Location ID:318383



Photo 1 not tracking pad onto asphalt.



Photo 2 access road has deep ruts no BMP's in place or maintenance performed.

Inspection Photos
Location Name: UPRR 43 pan AM I#25
Location ID:318383



Photo 3 No BMP's in place along backfilled ditch. Area is not seeded or graded.



Photo 4 Unused equipment: Electric panel. Cement base

Inspection Photos
Location Name: UPRR 43 pan AM I#25
Location ID:318383



Photo 5 Unused equipment: Electric panel meter has been pulled.



Photo 6 No BMP's in place on backfilled ditch.

Inspection Photos
Location Name: UPRR 43 pan AM I#25
Location ID:318383



Photo 7 Well is with in 100 feet of homes.



Photo 8 Well head flow line valves is the closed position.