

# Inspection Photos

API: 071-06902

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/19/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06902 | Date: 10/19/2021

## Inspection Photos



**Photo 1.** Facing southwest along the main road to the well site. There is erosion along the road which is causing sediment accumulation at the culvert and at the main road in Lorencito Canyon. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06902 | Date: 10/19/2021



## Inspection Photos



**Photo 2.** Facing back down from the previous photos shows the stormwater erosion which is directed toward the culvert and towards the main Lorencito road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06902 | Date: 10/19/2021



## Inspection Photos



**Photo 3.** Facing northeast along the access road to the well site. There is an erosion channel across the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06902 | Date: 10/19/2021

## Inspection Photos



**Photo 4.** Facing northeast toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06902 | Date: 10/19/2021