

**Inspection Photos**  
**Operator: Hilcorp Energy**  
**API: 067-08479**  
**Date: 10/19/2021**



Photo 1. View of the project area from the northwestern corner facing center facing center.



Photo 2. View of the western fill slope from the northwestern corner facing southward. Revegetation is progressing largely with western wheatgrass.



Photo 3. View of erosional rilling and channeling, approx. 1-2ft wide and deep at the well pad entrance, facing up-slope. This occurs where concentrated stormwater flows off of the well pad.



Photo 4. View of erosional channel, facing down-slope from photo 3, approx. 2ft wide and deep.



Photo 5. View of the reference area comprised of ponderosa pine forest with understory of gambel oak, serviceberry, Oregon grape, western wheatgrass, and muttongrass.