

Inspection Photos
Operator: Hilcorp Energy
API: 067-07683
Date: 10/19/2021



Photo 1. View of unreclaimed well pad from the well pad entrance facing center.



Photo 2. View of dense Canada thistles within the eastern project area. Approximately 2000 individuals observed.



Photo 3. View of project equipment that remains on the well pad.



Photo 4. View of bare soils on the southern cut-slope, project area needs recontouring and stabilization.



Photo 5. View of access road that remains in place.



Photo 6. View of the reference area comprised of ponderosa pine forest with understory of gambel oak, serviceberry, Oregon grape, western wheatgrass, and muttongrass.