

Inspection Photos

Operator: Hilcorp Energy
API: 067-07645
Date: 10/19/2021



Photo 1. View of the project area from the northern portion of the bisecting road, facing center. Well marker present in the center of photo.



Photo 2. View of View of the eastern project area facing northward. Little desirable vegetation present. Vegetation is largely comprised of weeds such as Russian thistle and knotweed.



Photo 3. Birdseye view of typical revegetation within the project area.



Photo 4. View of area in the southeastern well pad area where sparse grasses are becoming established. Rilling is occurring on bare soils that are not stabilized.



Photo 5. View of Russian thistle debris observed on the well pad and along the northern boundary of the well pad (inset). Needs to be removed.



Photo 6. View of the reference area comprised of ponderosa pine forest with understory of gambel oak, serviceberry, Oregon grape, western wheatgrass, and muttongrass.