

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/12/2021

Submitted Date:

10/12/2021

Document Number:

699503255

FIELD INSPECTION FORM
 Loc ID 320477 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10711

Name of Operator: PAINTED PEGASUS PETROLEUM LLC

Address: 16820 BARKER SPRINGS RD #521

City: HOUSTON State: TX Zip: 77084

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
		khubbard@p3petro.com	
		jh@p3petro.com	
		dnr_cogccengineering@state.co.us	
		jm@p3petro.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257347	WELL	SI	09/01/2019	OW	001-09416	ABBOTT 12-21	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

Weeds are unmanaged on location. Unable to visually inspect berms, and netting on open top tank due to weed growth. Stained soil, trash by tanks needs to be removed. Separator near wellhead needs to be removed.

Corrective Action:

Comply with COGCC housekeeping rules 1/22/21

Date: 01/22/2021

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bird Protectors

2

Comment:

Corrective Action:

Date:

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Marked with metal pole

Corrective Action:

Date:

Type: Pig Station

1

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:	Automation		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
	1		Open Top		,	
Comment:	Unable to inspect netting due to weed growth on location					
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Unable to visually inspect due to weed growth on location				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment:	Unable to visually inspect berms due to weed growth on location				
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 257347 Type: WELL API Number: 001-09416 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 05/14/2020 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0Comment: Annual Bradenhead test is not current. Contact COGCC engineering 10/21/2021Corrective Action: A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. Date: _____**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 10/11/21 at approximately 1430 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Abbott 12-21</p> <p>Company Name- Painted Pegasus</p> <p>API- 05-001-09416</p> <p>In Adams County Colorado.</p> <p>While there, I observed SI well</p> <p>This is a follow up inspection from document #700900419 Corrective Actions are Delinquent</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds are unmanaged on location. Unable to visually inspect berms, and netting on open top tank due to weed growth. Stained soil, trash by tanks needs to be removed. Separator near wellhead needs to be removed.</p> <p>Comply with COGCC housekeeping rules 1/22/21</p> <p>Annual Bradenhead test is not current. Contact COGCC engineering</p> <p>Comply with COGCC annual bradenhead testing rules. 10/21/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	10/12/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402843693	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5556549
699503256	Inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5556535