

**Inspection Photos**  
**Location Name: UPRR 42 Pan AM I #5**  
**Location ID: 318212**



**Photo 1 Well head.**



**Photo 2 Well head**

**Inspection Photos**  
**Location Name: UPRR 42 Pan AM I #5**  
**Location ID: 318212**



**Photo 3 Straw waddles not properly installed.**



**Photo 4 no excavation BMP's. No Disturbed area BMP's**



**Inspection Photos**  
**Location Name: UPRR 42 Pan AM I #5**  
**Location ID: 318212**



**Photo 5 No location or excavation BMP's**



**Photo 6 open excavation**



**Inspection Photos**  
**Location Name: UPRR 42 Pan AM I #5**  
**Location ID: 318212**



**Photo 7 Waddles removed to haul off contaminated soil not staking material on site.**



**Photo 8 Loc pic**

**Inspection Photos**  
**Location Name: UPRR 42 Pan AM I #5**  
**Location ID: 318212**



**Photo 9 loc pic**