

Inspection Photos
Operator: Simcoe
API: 067-06328
Date: 10/22/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with a mixture of wheatgrasses and irrigated grasses such as orchard grass.



Photo 3. View of cable debris in the southeastern portion of the project area, needs to be removed.



Photo 4. View of the reference area comprised of irrigated grass field with grasses such as smooth brome, orchard grass, and foxtail barley, as well as scattered wetland vegetation such as cattails and rushes.