

Inspection Photos

Location Name: CAERUS PICEANCE LLC ST. PARACHUTE TBI-67S96W /36NESW

Location ID: 334084



Photo #5122 from entrance to location.



Photo #5123 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ST. PARACHUTE TBI-67S96W /36NESW

Location ID: 334084



Photo #5124 No battery sign located at the tank battery.



Photo #3824 from inspection #699803088 conducted on 5/17/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ST. PARACHUTE TBI-67S96W /36NESW

Location ID: 334084



Photo #5125 Glycol tank missing required information.



Photo #5126 Heating insulation open ended and not capped.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ST. PARACHUTE TBI-67S96W /36NESW

Location ID: 334084



Photo #5127 Heating insulation open ended and not capped.



Photo #5128 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ST. PARACHUTE TBI-67S96W /36NESW

Location ID: 334084



Photo #5129 Location lacks stabilization.



Photo #3826 from inspection #699803088 conducted on 5/17/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ST. PARACHUTE TBI-67S96W /36NESW

Location ID: 334084



Photo #5130 No form of tracking BMP located at entrance to location.



Photo #3824 from inspection #699803088 conducted on 5/17/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ST. PARACHUTE TBI-67S96W /36NESW

Location ID: 334084



Photo #5131 Rill erosion occurring on cut slope.



Photo #5132 Run on to location is not being controlled.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ST. PARACHUTE TBI-67S96W /36NESW

Location ID: 334084



Photo #5133 Sediment encroaching on equipment.