

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2021

Submitted Date:

10/19/2021

Document Number:

700703391

FIELD INSPECTION FORM

Loc ID 335694 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

4 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
Thomson, Bud		BLThomps@BLM.gov	
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281423	WELL	PR	07/08/2010	GW	103-10646	PICEANCE CREEK UNIT T35X-2G9	PR
281424	WELL	PR	08/25/2009	GW	103-10647	PICEANCE CREEK UNIT T35X-2G8	PR
281427	WELL	PR	07/01/2021	GW	103-10648	PICEANCE CREEK UNIT T35X-2G7	PR
281428	WELL	PR	02/09/2010	OG	103-10649	PICEANCE CREEK UNIT T35X-2G6	PR
281429	WELL	PR	06/22/2008	GW	103-10650	PICEANCE CREEK UNIT T35X-2G5	PR
281430	WELL	PR	06/08/2012	GW	103-10651	PICEANCE CREEK UNIT T35X-2G4	PR
281431	WELL	PR	08/01/2021	GW	103-10652	PICEANCE CREEK UNIT T35X-2G3	PR
281432	WELL	PR	06/22/2008	GW	103-10653	PICEANCE CREEK UNIT T35X-2G2	PR
281433	WELL	PR	12/01/2020	GW	103-10654	PICEANCE CREEK UNIT T35X-2G1	PR

General Comment:

COGCC Inspection Report Summary

On Monday 10/18/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus PCU T35X-2G, at Location # 335694 in Rio Blanco county Colorado.

While there, I observed normal operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Fill slope shows signs of erosion/sediment migration
2. One dead man is improperly marked
3. Chemical tank containments are full of fluid and would not be sufficient to contain possible spill
4. Lack of battery signage

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Comply with rule 605.e		Date: 12/24/2021
Type	OTHER		
Comment:	Entrance to location		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Chemical tank containments are full of fluid and would not be sufficient to contain possible spill		
Corrective Action:	provide adequate space in containment to contain possible spill		Date: 10/29/2021

Overall Good:

Spills:			
Type	Area	Volume	
In Containment:	No		
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Bradenhead	# 9		
Comment:			
Corrective Action:			Date:

Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 1		
Comment:	One dead man is improperly marked		
Corrective Action:	Mark or remove dead man		Date: 11/19/2021
Type: Ancillary equipment	# 2		
Comment:	chemical tanks in plastic containments		
Corrective Action:			Date:
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	281423	Type:	WELL	API Number:	103-10646	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	281424	Type:	WELL	API Number:	103-10647	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	281427	Type:	WELL	API Number:	103-10648	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	281428	Type:	WELL	API Number:	103-10649	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	281429	Type:	WELL	API Number:	103-10650	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	281430	Type:	WELL	API Number:	103-10651	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	281431	Type:	WELL	API Number:	103-10652	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	281432	Type:	WELL	API Number:	103-10653	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				

Facility ID: 281433 Type: WELL API Number: 103-10654 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				

Comment: 1. Fill slope shows signs of erosion/sediment migration

Corrective Action: Install or repair required BMPs

Date: 12/24/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402847008	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5559271
700703395	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5559268