

Inspection Photos

API: 061-05138

Operator: WESTERN OPERATING COMPANY

Inspection Date: 10/27/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 10/27/2021

Inspection Photos



Photo 1. Facing east at the beginning of the access road. The two track road remains with compacted soils. The access road needs to be recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 10/27/2021

Inspection Photos



Photo 2. Facing north along the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 10/27/2021

Inspection Photos



Photo 3. Facing northwest toward the former tank battery site located 300' southwest of the well site. This area has not been reclaimed. Bare soils that are not stabilized and are susceptible to further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 10/27/2021

Inspection Photos



Photo 4. There is a pipe riser that remains at the battery site. All abandoned risers need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 10/27/2021

Inspection Photos



Photo 5. There are two pipes that remain at the battery site that need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 10/27/2021

Inspection Photos



Photo 6. Facing southwest toward the abandoned battery site which was never reclaimed. Bare soils that are not stabilized and are susceptible to further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 10/27/2021

Inspection Photos



Photo 7. There are additional abandoned risers that remain at the tank battery site. All abandoned risers need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 10/27/2021

Inspection Photos



Photo 8. Facing northeast toward the abandoned well site. This area has not been reclaimed. Bare soils that are not stabilized and are susceptible to further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 10/27/2021

Inspection Photos



Photo 9. Facing south toward the abandoned well site. This area has not been reclaimed. Bare soils that are not stabilized and are susceptible to further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 10/27/2021