

Inspection Photos
Operator: Simcoe
API: 067-07858
Date: 10/27/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is failed here, and infested with musk thistle. Approx. 2000 musk thistles observed. Reclamation is needed.



Photo 3. View of dense musk thistles in post-flowering condition, as well as rosettes.



Photo 4. View of the reference area comprised of irrigated grass field with grasses such as meadow brome, orchard grass, perennial ryegrass, as well as wetland vegetation such as cattails, rushes, and foxtail barley.