

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/13/2021

Submitted Date:

10/29/2021

Document Number:

700900815

FIELD INSPECTION FORM

Loc ID 319972 Inspector Name: Finkenbinder, Chane On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10695
Name of Operator: BEHRENS RESOURCES INC
Address: PO BOX 188
City: DEER TRAIL State: CO Zip: 80135

Findings:

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|----------------------------------|--|
| | | dnr_cogccenforcement@state.co.us | For CA Matrix Inspection Routing |
| | | conor.pesicka@state.co.us | |
| Behrens, Vic | 303-810-6382 | behrens@netecin.net | Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 202061 | WELL | SI | 06/01/2018 | GW | 001-07466 | FARM RANCH EXPLORATION 1 | SI |

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|--|-------------------------|
| Type | WEEDS | | |
| Comment: | <u>Weeds throughout the location.</u> | | |
| Corrective Action: | <u>Location is within a designated setback location, remove trash, debris and weeds per Rule 606. Corrective Action Date 11/18/2021. See attached photo # 1 through 8</u> | | Date: <u>11/18/2021</u> |

Overall Good:

Spills:

| Type | Area | Volume | |
|------|------|--------|--|
| | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type | # | Comment | Corrective Action | Date | corrective date |
|---------------------------------|-----|---|-------------------|-------------------------|-----------------|
| Type: Deadman # & Marked | # 4 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | |
| Type: Emission Control Device | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | |
| Type: Bradenhead | # 1 | | | | |
| Comment: | | <u>Appears to be plumbed to surface</u> | | | |
| Corrective Action: | | | | | |
| Type: Pump Jack | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | |
| Type: Bird Protectors | # 2 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | |
| Type: Vertical Heated Separator | # 1 | | | | |
| Comment: | | <u>Stained soil around the separator.</u> | | | |
| Corrective Action: | | <u>Control and contain spills/releases and clean up per Rule 912.aContact COGCC EPS staff. Immediately to stop and clean up 24 hours to remove free fluids. . Corrective Action Date 11/18/2021 to remove stained soil. See attached photo #5</u> | | | |
| | | | | Date: <u>11/18/2021</u> | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------|---|-----------|----------|---------|--------|
| PRODUCED WATER | 1 | <100 BBLS | Open Top | | |
| Comment: | | | | | |

| | |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

Paint

| | | | |
|------------------|----------|--|--|
| Condition | Adequate | | |
| Other (Content) | | | |
| Other (Capacity) | | | |
| Other (Type) | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | 39.833509,-104.536447 |
| Comment: | | | | | |
| Corrective Action: | | | | | |
| | | | | | Date: |

Paint

| | | | |
|------------------|----------|--|--|
| Condition | Adequate | | |
| Other (Content) | | | |
| Other (Capacity) | | | |
| Other (Type) | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Wells Served By Facilities Above

| API Number |
|------------|
| 001-07672 |
| 001-07466 |
| 001-07888 |

AirsID

| API Number | AirsID |
|------------|--------|
|------------|--------|

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 202061 Type: WELL API Number: 001-07466 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Appears to be plumbed to surface

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| <p>COGCC Inspection Report Summary On Wednesday October 13, 2021 at approximately 10:30am. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Farm Ranch Exploration 1, Behrens Resources INC. at API # 001-07466 in Adams County Colorado. While there, I observed a producing well. During this inspection the following possible compliance issues were observed: No Actions have been taken from doc #700900615 Weeds throughout the location. Location is within a designated setback location, remove trash, debris and weeds per Rule 606. Corrective Action Date 11/18/2021. See attached photo # 1 through 8 Stained soil around the separator. Control and contain spills/releases and clean up per Rule 912.aContact COGCC EPS staff. Immediately to stop and clean up 24 hours to remove free fluids. . Corrective Action Date 11/18/2021 to remove stained soil. See attached photo #5 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | finkenbc | 10/29/2021 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 700900816 | reinspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5567742 |