

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2021

Submitted Date:

10/30/2021

Document Number:

688311424

**FIELD INSPECTION FORM**Loc ID 433780 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96340

Name of Operator: WIEPKING-FULLERTON ENERGY LLC

Address: 106 GLENMOOR LN

City: ENGLEWOOD State: CO Zip: 80113

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name   | Phone          | Email                | Comment         |
|----------------|----------------|----------------------|-----------------|
| Halde, Kerry   | (719) 340-0329 | haldeoil@hotmail.com | All Inspections |
| Shalberg, Greg | (719) 688-3547 | gregshalberg@aol.com |                 |
| Boone, Linda   | (720) 271-8605 | LDBoonePar@aol.com   | All Inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 433781      | WELL | PR     | 06/01/2020  | OW         | 073-06548 | Nemesis 2     | PR          |

**General Comment:**

Routine Field Inspection

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | CONTAINERS           |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 719-340-0329

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               | OTHER                                  |       |  |
| Comment:           | location, TB and access road are mowed |       |  |
| Corrective Action: |  | Date: |  |

Overall Good: ☐

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Type               | LOCATION     |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | WELLHEAD     |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | PUMP JACK    |       |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Equipment:**

|                               |                                    |       |                 |
|-------------------------------|------------------------------------|-------|-----------------|
| Type: Emission Control Device | # 1                                |       | corrective date |
| Comment:                      |                                    |       |                 |
| Corrective Action:            |                                    | Date: |                 |
| Type: Deadman # & Marked      | # 4                                |       |                 |
| Comment:                      |                                    |       |                 |
| Corrective Action:            |                                    | Date: |                 |
| Type: Pump Jack               | # 1                                |       |                 |
| Comment:                      |                                    |       |                 |
| Corrective Action:            |                                    | Date: |                 |
| Type: Vertical Heater Treater | # 1                                |       |                 |
| Comment:                      |                                    |       |                 |
| Corrective Action:            |                                    | Date: |                 |
| Type: Bird Protectors         | # 2                                |       |                 |
| Comment:                      |                                    |       |                 |
| Corrective Action:            |                                    | Date: |                 |
| Type: Gas Meter Run           | # 1                                |       |                 |
| Comment:                      | no calibration card is needed      |       |                 |
| Corrective Action:            |                                    | Date: |                 |
| Type: Prime Mover             | # 1                                |       |                 |
| Comment:                      | gas engine                         |       |                 |
| Corrective Action:            |                                    | Date: |                 |
| Type: Bradenhead              | # 1                                |       |                 |
| Comment:                      | 2021 Form 17 is in COGCC database. |       |                 |
| Corrective Action:            |                                    | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | 300 BBLS | FIBERGLASS AST |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|      |          |                     |                     |             |

|                    |   |                                     |           |         |        |       |  |
|--------------------|---|-------------------------------------|-----------|---------|--------|-------|--|
| Comment:           |   | same earth berms as crude oil tanks |           |         |        |       |  |
| Corrective Action: |   |                                     |           |         |        | Date: |  |
| Contents           | # | Capacity                            | Type      | Tank ID | SE GPS |       |  |
| CRUDE OIL          | 3 | 300 BBLs                            | STEEL AST |         | ,      |       |  |
| Comment:           |   |                                     |           |         |        |       |  |
| Corrective Action: |   |                                     |           |         |        | Date: |  |

**Paint**

|                  |          |  |  |  |  |  |  |
|------------------|----------|--|--|--|--|--|--|
| Condition        | Adequate |  |  |  |  |  |  |
| Other (Content)  |          |  |  |  |  |  |  |
| Other (Capacity) |          |  |  |  |  |  |  |
| Other (Type)     |          |  |  |  |  |  |  |

**Berms**

|                    |          |                     |                     |             |  |       |  |
|--------------------|----------|---------------------|---------------------|-------------|--|-------|--|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |  |       |  |
| Earth              | Adequate |                     |                     |             |  |       |  |
| Comment:           |          |                     |                     |             |  |       |  |
| Corrective Action: |          |                     |                     |             |  | Date: |  |

**Wells Served By Facilities Above****AirsID**

|            |            |        |
|------------|------------|--------|
| API Number | API Number | AirsID |
| 073-06548  |            |        |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

### Location Construction

Location ID: 433781 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

#### Form 2A COAs:

**Comment:** No problems seen.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

#### Wildlife BMPs:

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ Date: \_\_\_\_\_

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

|                             |  |                       |            |                  |
|-----------------------------|--|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |  |                       |            |                  |
| Facility ID: 433781         | Type: WELL   | API Number: 073-06548 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |  |                       |            |                  |
| Comment:                    | pr 8/1/2021 production reported to COGCC database. |                       |            |                  |
| Corrective Action:          |  |                       |            | Date:            |

|  |
|--|
|  |
|--|

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  | Material Handling And Spill Prevention | Fail                     |         |
| Gravel           | Pass            | Gravel                  | Pass                  |  |                          |         |

Comment: See attached photo at PU engine. No sure what this is, determine proper response.  
See attached photos of vegetation at well location. Vegetation compares to background.

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.

Date: 12/03/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                  | URL   |
|--------------|------------------------------|---|
| 688311490    | Wiepking-Fullerton Nemesis 2 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568669">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568669</a> |