

Inspection Photos

API: 017-06098

Operator: PRONGHORN OPERATING

Inspection Date: 10/26/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06098 | Date: 10/26/2021

Inspection Photos



Photo 1. Center of the location facing north. The desirable vegetation has established to reflect reference area levels.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06098 | Date: 10/26/2021

Inspection Photos



Photo 2. Center of the location facing west. The desirable vegetation has established to reflect reference area levels.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06098 | Date: 10/26/2021

Inspection Photos



Photo 3. Center of the location facing south. The desirable vegetation has established to reflect reference area levels.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06098 | Date: 10/26/2021

Inspection Photos



Photo 4. Center of the location facing east. The desirable vegetation has established to reflect reference area levels.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06098 | Date: 10/26/2021

Inspection Photos



Photo 5. View of groundcover at the location shows perennial desirable vegetation consisting of Buffalo grass, Western wheat grass, among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06098 | Date: 10/26/2021