

Inspection Photos
Operator: Simcoe
API: 067-09325
Date: 10/27/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is sparse and progressing similar to surrounding grazed pasture. Revegetation should be assessed during the active growing season.



Photo 3. View of erosional rilling, approximately 8-10 inches wide and deep, within the southern project area.



Photo 4. View of the reference area comprised of open field, upslope from irrigation ditch, in grazed vegetative condition at this time.