

Inspection Photos

11/01/2021

Operator: NONSUCH NATURAL GAS INC

#10163

Location ID: 324169

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC #10163
Location ID: 324169



Photo 1: Photo show wildlife protection devices to prevent wildlife access to the secondary containment BMPs are missing.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



Photo 2: Photo taken from the interim areas on the west end of the Location. Unable to find evidence that additional reclamation was performed; reclamation not progressing towards 1003 standards. Photo also shows control measures to protect/stabilize the cut/fill slopes of the Location, and to prevent offsite sediment transport remains missing or insufficient.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



November 1, 2021
39.51373607N 108.19974872W



November 1, 2021
39.51380796N 108.19972913W

Photo 3: Photo taken from the interim areas on the east end of the Location. Unable to find evidence that additional reclamation was performed; reclamation not progressing towards 1003 standards. Photo also shows control measures to protect/stabilize the cut/fill slopes of the Location, and to prevent offsite sediment transport remains missing or insufficient.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



Photo 4: Photos show erosion degradation along the access road; control measures to stabilize, manage runoff, and minimize erosion remain missing or insufficient at the access road; erosion degradation and offsite sediment transport observed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



Photo 5. Photos show erosion degradation along the access road; control measures to stabilize, manage runoff, and minimize erosion remain missing or insufficient at the access road; erosion degradation and offsite sediment transport observed.