

Inspection Photos
Location Name: UPRR 43 Pan AM I #19
Location ID: 332976



Photo 1 loc pic Unused equipment electric panel and road leveler

Photo 2 Access road appears to be plowed over by farmer

Inspection Photos
Location Name: UPRR 43 Pan AM I #19
Location ID: 332976



Photo 3 Unused equipment road leveler clearly says KPK