

Inspection Photos

11/01/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 452807

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 452807



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east. Photos also show interim reclamation has not been conducted on the location in accordance with 1003 rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 452807



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 452807



Photo 3: Photos provide examples of the steep, rocky fill slopes on the Location. Previous inspections required Operator to implement control measures to protect and stabilize the slopes of the Location; Operator implemented hydromulch on the slopes of the Location. Hydromulch is inadequate to stabilize the fill slopes due to the Location's steep grade and rocky conditions; BMP inadequate per the site's conditions.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 452807



November 1, 2021
39.55781306N 108.20515577W

Photo 4: Photo taken from the cut slopes of the Location; hydromulch has been applied to the exposed soils on the cut slope. Hydromulch is a temporary control; ensure BMP is maintained in proper functioning condition.