

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 3: UNUSED EQUIPMENT (ENGINE SKID FOR TA WELL).		
Corrective Action:	REMOVE UNUSED EQUIPMENT PER RULE 606. THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION.	Date:	02/25/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Prime Mover	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	BOTH ARE PLUMBED TO SURFACE		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 89154 Type: WELL API Number: 071-06733 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 217693 Type: WELL API Number: 071-06472 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In

Temporarily Abandoned

Reminder: _____

Comment: LAST MIT 9-19-19

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:
 Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: _____ Lat: 37.227480 Long: -104.689310
 Reference Point: SE Other: _____ Length: 50 Width: 50

Lining:
 Liner Type: _____ Liner Condition: _____
 Comment:
 Corrective Action Date: _____

Fencing:
 Fencing Type: None Fencing Condition: _____
 Comment:
 Corrective Action Date: _____

Netting:
 Netting Type: _____ Netting Condition: _____
 Comment: NONE
 Corrective Action Date: _____
 Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES
 Comment:
 Corrective Action Date: _____

COGCC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC#695103622, THE CA FOR WELL SIGN WAS A MISTAKE THE WELLSIGN IS ON THE BACKSIDE OF THE METER HOUSE. THE CA FOR UNUSED EQUIPMENT WAS NOT ADDRESSED THIS IS THE SECOND NOTICE ON THIS CORRECTIVE ACTION.	beardslt	10/28/2021
THERE IS NO PIT PERMIT IN COGCC RECORDS. CONTACT EPS TO RESOLVE THE ISSUE.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402856926	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5567413
695105063	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5567267