

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2021

Submitted Date:

10/28/2021

Document Number:

696203316

FIELD INSPECTION FORM

 Loc ID 323866 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num:
Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: PO BOX 370
 City: PARACHUTE State: CO Zip: 81635
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
 2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
323866	LOCATION	AC			-	YOUBERG-67S94W 12NWNE	RI

General Comment:

On 10/25/2021, Reclamation Specialist Trujillo conducted a stormwater inspection at TEP Rocky Mountain's Youberg-67S94W 12NWNE location in Garfield County, Colorado.

This inspection is a followup to #696203205 to document compliance for the following corrective actions:
 1002.f: Stormwater

It was observed in this inspection that the Location remains out of compliance with COGCC rules and corrective actions.

Refer to inspection #696203205 for corrective actions regarding interim reclamation

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:	#		corrective date
Comment:	Inspection #696203205 observed that control measures to prevent wildlife access to the containment BMP at the tank on the west end of the Location are missing or insufficient. Inspection required Operator to install or repair wildlife protection equipment.		
	It was observed in this inspection that Operator has placed a board into the containment BMP; control measures to prevent wildlife access to the containment BMP remains inadequate.		
Corrective Action:	Install or repair wildlife protection equipment.		Date: <u>11/12/2021</u>

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 323866 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #696203205 observed that the stormwater diversion ditch on the western perimeter of the Location has not been constructed with an appropriate outlet in accordance with good engineering practices; runoff from ditch causing erosion degradation on the north end of the Location. Inspection required Operator to comply with Rule 1002.f by 10/19/2021.

It was observed in this inspection that the stormwater diversion ditch remains improperly constructed without an appropriate outlet per good engineering practices; BMPs to prevent offsite stormwater degradation remain missing or insufficient.

Corrective action and date remains applicable.

Corrective Action: **Comply with Rule 1002.f**

Date: 10/19/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402855871	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5566481
696203317	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5566465