

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2021

Submitted Date:

11/04/2021

Document Number:

688801018**FIELD INSPECTION FORM**Loc ID 378515 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 39166Name of Operator: HEFNER & CHRIST

Address: \_\_\_\_\_

City: DENVER State: CO Zip: \_\_\_\_\_**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Chollett, Shannon		shannon.chollett@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205061	WELL	DA	02/24/1951	DA	007-05170	SHAHAN (OWP) 2	EI

**General Comment:**

On October 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hefner & Christ Shahan (OWP) #2. For the most recent field inspection report of this facility please refer to document #669500233. OWP work related to this facility is scheduled to begin in the fall of 2021 with work proceeding under Remediation Project #20502.

**Location****Lease Road:**

Type	Access		
comment:	Access from private drive off of Highway 84. Well head is located in adjacent field.		
Corrective Action:		Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Environmental****Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: \_\_\_\_\_

Comment: Pool of water observed around well. Soil has been removed from around well since last site visit by SW EPS.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 12/04/2021

Reportable: NO

GPS: Lat 37.038345

Long -106.842857

Proximity to Surface Water:

Depth to Ground Water:

**Water Well Complaint:**

Lat

Long

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On October 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hefner &amp; Christ Shahan (OWP) #2. For the most recent field inspection report of this facility please refer to document #669500233. OWP work related to this facility is scheduled to begin in the fall of 2021 with work proceeding under Remediation Project #20502.</p> <p>During this inspection a pool of stagnant water was observed around the well casing, no flow was observed.</p> <p>Soil had been removed from around the well since the last site visit.</p>	hughesjo	11/04/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801019	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5572540">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5572540</a>