

Inspection Photos

11/01/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 383337

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 383337



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location from south, southwest, northwest to north. Photos also show interim reclamation of areas not needed for production has been performed or is in process; Operator observed applying hydromulch/hydroseed to the southern interim areas at time of inspection.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 383337



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 383337



November 1, 2021
39.53612857N 108.23727342W



November 1, 2021
39.53596071N 108.23744159W

Photo 3: Photos taken from the production area and provide examples showing control measures to stabilize the Location, and mitigate tracking and offsite sediment transport are missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 383337



November 1, 2021



November 1, 2021
39.53616547N 108.23793939W

Photo 4: Photos taken from the production area and provide examples showing control measures to stabilize the Location, and mitigate tracking and offsite sediment transport are missing or insufficient. Photo on left shows Location entrance to the well pad.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 383337



Photo 5: Photo taken from the sediment trap outlet on the east end of the Location. BMP has not been constructed in accordance with good engineering practices and is missing proper armoring and protection at the outlet spillway. Control is inadequate to allow for proper stormwater discharge.