

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2021

Submitted Date:

11/04/2021

Document Number:

688801020**FIELD INSPECTION FORM**Loc ID 440411 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 99999Name of Operator: OLD OPERATORS - STATUS UNKNOWNAddress: SEE COMMENT LINE IN WELLCity: XXXXXXX State: XX Zip: _____**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Chollett, Shannon		shannon.chollett@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440410	WELL	TA	07/07/2015	OW	007-40037	Underwood Ditch (OWP) 5	EI

General Comment:

On October 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Old Operators – Status Unknown Underwood Ditch (OWP) #5. For the most recent field inspection report of this facility please refer to document #685305007. OWP work related to this facility is scheduled to begin in the fall of 2021 with work proceeding under Remediation Project #20494.

Location**Lease Road:**

Type	Access		
comment:	Location is adjacent to private driveway off of Highway 84.		
Corrective Action:		Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	440410	Type:	WELL	API Number:	007-40037	Status:	TA	Insp. Status:	EI

--

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: Water actively flowing from casing during this inspection. Fluid flows approximately 100' south of well.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 12/04/2021

Reportable: _____

GPS: Lat 37.040120

Long -106.841880

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On October 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Old Operators – Status Unknown Underwood Ditch (OWP) #5. For the most recent field inspection report of this facility please refer to document #685305007. OWP work related to this facility is scheduled to begin in the fall of 2021 with work proceeding under Remediation Project #20494. Fluid was actively flowing from the casing during this inspection.	hughesjo	11/04/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801021	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5572619