

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/27/2021

Submitted Date:

11/04/2021

Document Number:

688801022

FIELD INSPECTION FORM
 Loc ID 440400 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 99999

Name of Operator: OLD OPERATORS - STATUS UNKNOWN

Address: SEE COMMENT LINE IN WELL

City: XXXXXXXX State: XX Zip:

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Chollett, Shannon		shannon.chollett@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440394	WELL	TA	07/07/2015	OW	007-40036	Underwood Ditch (OWP) 4	EI

General Comment:

On October 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Old Operators – Status Unknown Underwood Ditch (OWP) #4. For the most recent field inspection report of this facility please refer to document #685305006. OWP work related to this facility is scheduled to begin in the fall of 2021 with work proceeding under Remediation Project #20492.

Location**Lease Road:**

Type	Access		
comment:	Location is adjacent to private driveway off of Highway 84.		
Corrective Action	L	Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Length of steel cable located near well.		
Corrective Action:	Comply with Rule 606.	Date:	11/19/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	440394	Type:	WELL	API Number:	007-40036	Status:	TA	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On October 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Old Operators – Status Unknown Underwood Ditch (OWP) #4. For the most recent field inspection report of this facility please refer to document #685305006. OWP work related to this facility is scheduled to begin in the fall of 2021 with work proceeding under Remediation Project #20492. A section of steel cable is located near this well. Fluid was visible inside the casing during this inspection.	hughesjo	11/04/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801023	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5572634