

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/01/2021

Submitted Date:

11/04/2021

Document Number:

696203338

FIELD INSPECTION FORM

Loc ID 335889 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
5 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10433
 Name of Operator: LARAMIE ENERGY LLC
 Address: 1001 17TH STREET #1900
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
,		dnr_cogccenforcement@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335889	LOCATION	AC			-	Cascade Creek 697-09-61	RI

General Comment:

On 11/1/2021, Reclamation Specialist Trujillo inspected Laramie Energy LLCs' Cascade Creek 697-09-61 Location in Garfield County, Colorado.

This inspection is a followup to:
 #696201787 dated 9/16/2020;
 #696201980 dated 11/2/2020;
 #696202122 dated 12/8/2020;
 #696202928 dated 7/12/2021;
 #696203107 dated 8/23/2021;
 and #696203152 dated 9/8/2021 to document compliance with the following corrective actions on the Location:

-1002.f: Stormwater
 -606.c: Undesirable (noxious) plant species

This inspection is also in response to NOAV #402812356 issued 9/15/2021.

This inspection is solely for the Location and does not resolve any outstanding corrective actions associated with the Remediation Project #4620.

Refer to the "Location" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	<p>Previous inspections observed Undesirable (Noxious) plant species on the interim areas of the Location. Inspection required Operator to comply with Rule 606.c</p> <p>Noxious weeds not observed during inspection; corrective action appears to have been addressed.</p> <p>Continue to monitor and manage Undesirable Plant Species on the Location to prevent further spread and establishment. A followup inspection will be conducted in a future growing season to document compliance with Rule 606.c.</p>		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No _____

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 335889 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [See "COGCC Comments" for comments regarding Stormwater](#)

Corrective Action: **Install or repair required BMPs per Rule 1002.f.(2)C. Ensure control measures are adequate for the site's conditions, installed in accordance with good engineering practices, and maintained in proper functioning condition**

Date: 10/02/2020

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>STORMWATER COMMENT</p> <p>Previous inspections observed that Operator implemented erosion control blankets on the slopes of the north and west end of the Location; however, control measures to protect and stabilize a large section of cut slope remained missing or insufficient; inspections documented that corrective actions requiring compliance with Rule 1002.f were not addressed, and remain applicable.</p> <p>It was observed in this inspection that stabilization of the cut slope on the Location remains inadequate; control measures to protect, and stabilize the slopes remain missing or insufficient; erosion degradation evident.</p> <p>Erosion control blanket directly west of the unstabilized slope has not been maintained in proper functioning condition.</p> <p>Corrective actions have not been addressed and remain applicable.</p>	trujilloam	11/04/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696203341	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5572629