

Inspection Photos Operator:
Logos Operating
API: 067-05780
Date: 10/29/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of dense kochia and weed debris, up to 4 feet tall, observed throughout the working area and facilities.



Photo 3. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing with rubber rabbitbrush, western wheatgrass, and sand dropseed.



Photo 4. View of saltcedar (*Tamarisk* sp.) growing within the northern and western (inset) project area, that need to be removed. Approximately 15 individuals observed.



Photo 5. View of area in the western project area, approximately 50ft wide and long, where bare soils are eroding and need to be stabilized.



Photo 6. View of reference area comprised of open grass field, largely in a grazed vegetative condition, with grasses such as western wheatgrass and smooth brome.