

Inspection Photos
Operator: WPX
API: 067-05075
Date: 10/29/2021



Photo 1. View of the project area from the northern edge facing center. Revegetation is progressing, largely with crested wheatgrass.



Photo 2. View of the northern project area from the northeastern corner facing westward. Fencing is in place and needs to be removed, as well as Russian thistle debris.



Photo 3. View of the western project area, perennial grasses established, dense Russian thistle debris needs to be removed.



Photo 4. View of reference area comprised of open grass field with grasses such as smooth brome.