

Inspection Photos  
Operator: Hilcorp  
API: 067-07239  
Date: 10/29/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Vegetation is sparse and needs to be assessed during the active growing season.





Photo 3. View of equipment within the southwestern project area.





Photo 4. View of Russian knapweeds (approx. 200 individuals observed) within the eastern project area.





Photo 5. View of reference area comprised of pinyon and juniper woodland with understory of western wheatgrass and prickly pear.