

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2021

Submitted Date:

10/29/2021

Document Number:

688801012

FIELD INSPECTION FORMLoc ID 320912 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 900

Name of Operator: ALAMOSA DRILLING INC

Address: 8150 N. CENTRAL EXPY - STE 750

City: DALLAS State: TX Zip: 75205-

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schultz, Scott		scott.schultz@coag.gov	
Fischer, Alex		alex.fischer@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	All Inspections
Mercer, Lauren		lauren.mercer@coag.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296015	WELL	PR	09/01/2018	OW	007-06253	ALBERT MARTINEZ 1	EI
477321	Domestic Tap	AC	07/23/2020		-	Domestic Tap 18NENE	EI

General Comment:

On October 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Albert Martinez #1. For the most recent field inspection report of this facility, please refer to document #688800885.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Additional information required by Inspection Document #688800885 has been added to well head sign. Additional information part of sign has fallen off of sign post.			
Corrective Action:				Date:
Type	BATTERY			
Comment:	Additional information required by Inspection Document #688800885 has been added to tank battery sign.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	ASTs are labeled with contents, capacity, and have NFPA placards.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Emergency contact information has been added to location signage.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	DEBRIS			
Comment:	Pile of vegetative debris on location.			
Corrective Action:	Comply with Rule 606.			Date: 11/05/2021
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Perimeter post and wire fencing around pump jack and well head. Drop out tank for domestic tap is also fenced.			
Corrective Action:				Date:
Equipment:				
Type: Flow Line	# 1			corrective date
Comment:	Oil staining near elbow on flow line.			

Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date:	11/12/2021
Type: Prime Mover	# 1			
Comment:	Electric motor.			
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:	Operating during this inspection.			
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Domestic tap with drop out tank. Approximately 14 psi on gauge at drop out tank.			
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	HEATED STEEL AST		37.018609,-106.876678
Comment:	ASTs have been attached to anchors.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Shared secondary containment berm with Nielson #4. Location is within a defined floodplain in the COGIS database. Uncompacted earthen berm at tank battery.			
Corrective Action:	Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 421.b.(3). "Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 603.h.(2)C. Per phone conversation on 6/29, the operator shall provide documentation of COGCC exemption, ACE exclusion from mapped floodplain, and/ or design plans and time line for installation of steel ring secondary containment. Corrective action date taken from previous inspection to document days of noncompliance." Quoted text and corrective action date taken from Inspection Document #688800885.			Date:
				07/31/2018

Wells Served By Facilities Above**AirsID**

API Number	API Number	AirsID
007-06253		

Venting:

Yes/No	
--------	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 296015	Type: WELL	API Number: 007-06253	Status: PR	Insp. Status: EI
---------------------	------------	-----------------------	------------	------------------

Facility ID: 477321	Type: Domestic Tap	API Number: -	Status: AC	Insp. Status: EI
---------------------	--------------------	---------------	------------	------------------

COGCC Comments

Comment	User	Date
<p>On October 27, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Albert Martinez #1. For the most recent field inspection report of this facility, please refer to document #688800885.</p> <p>Additional information required by Inspection Document #688800885 has been added to well head sign.</p> <p>Additional information part of sign has fallen off of sign post.</p> <p>Additional information required by Inspection Document #688800885 has been added to tank battery sign.</p> <p>Emergency contact information has been added to location signage.</p> <p>Pile of vegetative debris on location.</p> <p>Shared secondary containment berm with Nielson #4. Location is within a defined floodplain in the COGIS database. Uncompacted earthen berm at tank battery.</p> <p>Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 421.b.(3).</p> <p>"Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 603.h.(2)C. Per phone conversation on 6/29, the operator shall provide documentation of COGCC exemption, ACE exclusion from mapped floodplain, and/ or design plans and time line for installation of steel ring secondary containment. Corrective action date taken from previous inspection to document days of noncompliance." Quoted text and corrective action date taken from Inspection Document #688800885.</p>	hughesjo	10/29/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402857959	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568455
688801013	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568454