

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2021

Submitted Date:

10/29/2021

Document Number:

690202227

FIELD INSPECTION FORM

 Loc ID 429093 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 10412
 Name of Operator: AUSCO PETROLEUM INC
 Address: 113 N SANTA FE AVENUE
 City: FLORENCE State: CO Zip: 81226
Findings:

- 6 Number of Comments
 5 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
HARKINS, LIZ		lharkins@austinexploration.com	
		dnr_cogccenforcement@state.co.us	
HART, TIMOTHY B		thart@fremontpetroleum.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429092	WELL	WO	08/20/2018	LO	043-06216	Pathfinder 1	RI
430103	WELL	SI	01/01/2020	GW	043-06221	Pathfinder 2	RI

General Comment:

This is a follow up of the previous inspections #690200750, #690201140, #690201452.
 The previous inspection corrective actions have not been performed.
 Non-compliance of the Rules will be referred to enforcement.
 See attached photos and additional details within this report.

Operator is directed to perform corrective actions outlined on this inspection report immediately. This inspection is being entered for notification and documentation only and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 523.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	There was trash debris being blown off site. There is trash containers tipped over and trash coming from the storage of supplies.		
Corrective Action:	Comply with Rule 606	Date:	11/03/2021
Type	OTHER		
Comment:	There is oil stained soil near the pumpjack and at the tank outlet which needs to be cleaned up. Previous corrective action was not performed.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes.	Date:	04/30/2021
Type	STORAGE OF SUPL		
Comment:	There is trailers, machinery and supplies being stored at the location. Storage of equipment, vehicle, trailers, supplies not necessary for use on the location is prohibited.		
Corrective Action:	Comply with Rule 606	Date:	11/12/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	The fence around the location is not maintained. Previous corrective action was not performed.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	02/18/2021

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail		Fail	Material Handling And Spill Prevention	Fail	

Comment: There is stormwater erosion occurring down the access road and into the drainage area. There are wattles displaced and not maintained. There is erosion occurring at the southwest and north side of the location where top perimeter ditch is concentrating stormwater. BMP's must be implemented in accordance with good engineering practice and must be maintained. Previous corrective action has not been performed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 11/11/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402857893	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568396
690202228	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568389