

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/28/2021

Submitted Date:

10/28/2021

Document Number:

693505681

FIELD INSPECTION FORM

Loc ID 318411 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	All Inspections
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241250	WELL	PR	04/01/2020	OW	123-09038	AMOCO-CHARTER-SCHNEIDER U A 12	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s)		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	11/28/2021

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Dead weeds on location and around equipment.		
Corrective Action:	Comply with rule 606	Date:	11/28/2021

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Steel pipe		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			

Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241250 Type: WELL API Number: 123-09038 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 06/16/2020 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 21 Fluid Type: _____End Surf Csg Pressure: 2Comment: Submit reports

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday October 28, 2021 at approximately 12:08 PM, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: Amoco-charter-Schnieder UA #12</p> <p>Operator: KP Kauffman</p> <p>API#: 123-09038</p> <p>County: Weld</p> <p>While there, I observed what appeared to a producing well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Debris: Rule 606 Corrective action date of 11-28-21 See photos 1,2,3,4</p> <p>Sign: Rule 605 d Corrective action date of 11-28-21 See photos 2,4</p> <p>Weather conditions: Windy.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	10/28/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402857132	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5567683
693505682	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5567668