

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/28/2021

Submitted Date:

10/29/2021

Document Number:

701003839

**FIELD INSPECTION FORM**

Loc ID 430234 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10460  
Name of Operator: HIGH PLAINS ENERGY LLC  
Address: 4545 S MONACO STREET #116  
City: DENVER State: CO Zip: 80237

**Findings:**

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Wheat, Randy	(720) 480-7776	rvwheat@comcast.net	
,		dnr_cogccengineering@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430233	WELL	TA	05/26/2017	OW	011-06200	BROWN 28-24-49 1	TA

**General Comment:**

Routine Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Elevated gravel road through pasture		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by wellhead. Update to current operator		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	11/28/2021

<b>Emergency Contact Number:</b>			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds all across location and on access to location		
Corrective Action:	Comply with Rule 1003.f.	Date:	11/28/2021

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 430233 Type: WELL API Number: 011-06200 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well is TA at time of inspection. Passing MIT performed 7/3/14. Well was found in state of Temporary Abandonment. Well is overdue for Mechanical Integrity Test (MIT). MITs require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b.

Corrective Action: Perform successful Mechanical Integrity Test. If a successful MIT can not be performed within 30 days of the CA time the well must be plugged within 3 months per Rule 417 and 210.

Date: 11/07/2021

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Culverts	Pass			
Gravel	Pass	Gravel	Pass			

Comment: A culvert was installed on the access for drainage during site preparation and is still currently in place. No work has been done to minimize site footprint. Topsoil remains onsite. Site is raised above ground level with berms around entire location for adequate erosion control measures. Vegetation is established where drilling pit was located. A pile of gravel on the east side of location is present at time of inspection. Access is an elevated gravel road. Location is on the south side of a drainage swale.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402857894	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568397">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568397</a>
701003845	location photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568394">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568394</a>